

## TEST CERTIFICATE

Henzi Tech GmbH, Maschinen- & Anlagenbau  
Fiechtlerweg 2, 4524 Günsberg

Tel. 032 637 14 46  
Fax 032 637 20 21

Order Number Henzi Tech: 180392  
Customer: Zürcher Technik AG Order number: 62020941  
Kind of test: helium leak detection Datum: 06/Apr/18

---

Test object: Ball Valve 20D DN25 FB  
Manufacturer: Henzi Tech GmbH, Fiechtlerweg 2, 4524 Günsberg  
Drawing number:  
Measuring unit: mbar .l. sek.

---

Test conditions according to customer specifications:

Vacuum inside . spray with helium on the outside  
1x in closed position, tightness in the passage  
1x in half open position, tightness spindle and housing seal

Pressure:  
Temperature: RT  
Medium: Helium

Maximum permissible leak rate: 10<sup>-5</sup>  
Process: vacuum inside . spray with helium on the outside

Used test equipment: ULTRATEST L 200  
Test equipment - mark: Do1247  
Audit findings: 10<sup>-7</sup>

Remarks: no

Test location Günsberg, 05/Apr/18

Tester: Christian Henzi

## TEST CERTIFICATE

Henzi Tech GmbH, Maschinen- & Anlagenbau  
Fiechtlerweg 2, 4524 Günsberg

Tel. 032 637 14 46  
Fax 032 637 20 21

Order Number Henzi Tech: 180392  
Customer: Zürcher Technik AG Order number: 62020941  
Kind of test: helium leak detection Datum: 06/Apr/18

---

Test object: Ball Valve 20D DN50 FB  
Manufacturer: Henzi Tech GmbH, Fiechtlerweg 2, 4524 Günsberg  
Drawing number:  
Measuring unit: mbar .l. sek.

---

Test conditions according to customer specifications:

Vacuum inside . spray with helium on the outside  
1x in closed position, tightness in the passage  
1x in half open position, tightness spindle and housing seal

Pressure:  
Temperature: RT  
Medium: Helium

Maximum permissible leak rate: 10<sup>-5</sup>  
Process: vacuum inside . spray with helium on the outside

Used test equipment: ULTRATEST L 200  
Test equipment - mark: Do1247  
Audit findings: 10<sup>-7</sup>

Remarks: no

Test location Günsberg, 05/Apr/18

Tester: Christian Henzi